Report of Surface Regularity

Warehouse 1

Calculated and analysed with
Flat 4

DRIVEN BY PRECISION



Prepared by: Andras Bodoczi Position: Senior Engineer

Document number: *GP-PRXXXXX_SR001* **Review number:** R01

Signed: 01/01/2020

Details of data collection

Site name: Warehouse1 Data registered by: John Doe

Date of registration: 01.01.2020 Floor number: Floor1

Slab number: SLAB-01 Point Cloud ID: Pointcloud.txt

Instruments used

Scanner:Leica P40Tag number:N/ATotal Station:N/ATag number:N/ADigital level:N/ATag number:N/A

Observations

Number of scans:115Max. scanning distance:15mScan resolution:6 mm/10mNumber of ground control points:N/A

Scan Quality

Registration accuracy:0.0006mRegistration check:PASSMax. control level deviation*:0.0009Level quality check:PASSGrid points created**:4441105Points failed classification:0Classifications*:N/AReady for calculation:PASS



Calculation results

Irregularity tolerances

Property A: 6mm over 1.5m **Property B:** 5mm over 2m (negative @1m)

Property C: 4mm over 1m (negative @0.5m) Step Tran.: N/A

Surface elevation

Design level:10.0000mHighest point:10.0172mAverage dev. from design:0.0030mLowest point:9.9702m

Statistics

Area of slab (m²): 11129.576 Calculation area (m²): 11102.76

Number of grid points in calculation: 4441105 Grid points failed tolerance: 295301



Error quantity

Number of grid points which exceeded tolerances and the affected area in relation to the type of irregularities.

Irregularity	Number of points	Area in m²	% of all	
Property A	292416	731.04	6.58	
Property B	18188	45.47	0.41	
Property C	2171	5.43	0.05	
Total	295197	738.30	6.66	

Different errors can occur at the same points.

Error severity


The different deviations in relation to the type of irregularities presented through the number of the affected points.


Irregularity	0-1mm	1-2mm	2-3mm	3-5mm	>5mm
Property A	175612	65009	26568	20848	4379
Property B	14782	2062	270	192	882
Property C	939	204	66	131	831
Total	188099	66799	26819	21088	5695

Different errors can occur at the same point
--


Status: TO BE GRINDED
















Explanation of error marks:

At projected error calculation (Property B,C) (Unit = as per Property specification)





At direct error calculation (Property A)

(Unit = as per Property specification)

